



SERVICE BULLETIN

RDR-1700 WEATHER RADAR SYSTEM

AA-1504A Antenna Array
P/N 4001943-0404

REASON FOR CHANGE:

Manufacturing error resulted in improper placement of caution decal.

Planning

EFFECTIVITY

This service bulletin is applicable to all AA-1504A Antenna Arrays, P/N 4001943-0404.


REASON

To insure that unit is properly installed.

DESCRIPTION and WORK INSTRUCTION


Units should be inspected to ascertain proper decal placement per the following illustrations. If decal was installed incorrectly, remove the decal and install a new decal in the proper orientation.

SERVICE BULLETIN



Incorrect Decal Placement

SERVICE BULLETIN



Correct Decal Placement

APPROVAL

This work does not revise the approved configuration; therefore, FAA or other regulatory agency approval is not required.

MANPOWER

Approximately 1.0 man-hours of labor is required to accomplish this work.

MATERIAL INFORMATION



SERVICE BULLETIN

The part required for this work is shown in the following table:

| Telephonics Part Number | Description | Qty |
|--------------------------------|--------------------|------------|
| 26232-0012 | Plate, Caution | 1 |

To order the required part, without charge, or for additional information - please contact:

Telephonics Corporation
815 Broad Hollow Road
Farmingdale, NY 11735
Attn: Product Support Department

Tel: 1-877-517-2327
1-631-755-7004

Fax: 1-877-755-7701
1-631-755-7227

Orders must specify part numbers, quantity required and reference this Service Bulletin.

REFERENCE

TM110402 RT-1700 Installation Manual

PUBLICATION AFFECTED -N/A

WARRANTY

Material will be covered for units in warranty.