



Command Systems Division  
Product Support Department  
815 Broad Hollow Road  
Farmingdale, NY 11735

---

## SERVICE LETTER

---

**Equipment Type(s):** RT-1401B

**Subject:** Recall of Units due to Manufacturing Error

**Affected Units:**

| RT Unit p/n  | Unit S/N | Modulator CCA p/n | CCA S/N |
|--------------|----------|-------------------|---------|
| 4000831-0106 | T2051    | 4007720-0501      | T2313   |
| 4000831-0106 | T2053    | 4007720-0501      | T2316   |
| 4000831-0106 | T2055    | 4007720-0501      | T2320   |
| 4000831-0106 | T2056    | 4007720-0501      | T2318   |
| 4000831-0105 | T2271    | 4007720-0501      | T2308   |
| 4000831-0105 | T2272    | 4007720-0501      | T2309   |
| 4000831-0105 | T2273    | 4007720-0501      | T2310   |
| 4000831-0105 | T2274    | 4007720-0501      | T2311   |
| 4000831-0105 | T2279    | 4007720-0501      | T2314   |

As these units may experience future malfunctions, customers with the above units are instructed to send the unit to the Telephonics factory or to an authorized Telephonics Service Center so that the unit can be restored to proper configuration prior to their return.

Please call the Telephonics Product Support department at 1-631-755-7004 for return instructions or for the location of the nearest authorized Telephonics Service Center.

Reference should be made to this service letter on the mailing label.



Command Systems Division  
Product Support Department  
815 Broad Hollow Road  
Farmingdale, NY 11735

For additional information contact:

Telephonics Corporation  
Command Systems Division  
Product Support Group  
815 Broad Hollow Road  
Attention: Mr. Kenneth Bernstein – Mail Stop 14  
Farmingdale, NY 11735  
Phone: 631-755-7081  
Fax: 1-631-755-7227  
e-mail: [bernstein@telephonics.com](mailto:bernstein@telephonics.com)