
SERVICE LETTER

Equipment Type(s): IN-2025B

Subject: Future Revision 10 to RDR-1400C (IN-2025B) Technical Manual

Issue: A replacement page 1-4A will be generated for Maintenance Manual Publication Number 006-05956-0009 dated July 1997 which adds the following additional Indicator part numbers to Table 1-1:

| TELEPHONICS PART NUMBER | TYPE | DESCRIPTION |
|----------------------------|----------|---|
| 4001670-2517 | IN-2025B | Same as -2511 except for 5V white lighting |
| 4001670-2518 | IN-2025B | Same as -2511 except for 28V white lighting and Freeze Mode |
| 4001670-2519 | IN-2025B | Same as -2511 except for 5V white lighting |
| 4001670-2520 | IN-2025B | Same as -2511 except for 28V NVIS green lighting |

Future TM Revision 10 is provided to accomplish this required coverage. This Service Letter can be downloaded from the Telephonics web site -www.telephonics.com . You may print this service letter and insert it into your manual as page 1-4A.

For additional information contact:
Telephonics Corporation
Command Systems Division
Product Support Group
815 Broad Hollow Road
Farmingdale, NY 11735 USA

Attention: Mr. Kenneth Bernstein – Mail Stop 18A

Phone: 1-631-755-7081 Fax: 1-631-755-7227
e-mail: bernstein@telephonics.com